

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Run date 22-Nov-14 8:08 AM Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 659 **Const Calendar Day:** 871 Date: 23-Oct-2014 Thursday Title: Transportation Engineer Inspector Name: Feather, Bernard

Inspection Type: Intermittent

Shift Hours: 07:00 am 04:00 pm **Break:** 01:00 Over Time:

Federal ID: Location:

Reviewer: Approved Date: Status: Submit Shedd, Bill

Weather			
Temperature 7 AM	12 PM	4PM	
Precipitation		Condition clear, cool	
Working Day 🗸 If no, exp	olain:		
Diary:			Dispute
General Comments			
Elevator inspection with diaries.	h Bill O'Sullivan and sign o	off punch list items. Misc MEP paperwork and write	
04-0120F4 Bid Item:	098 0-000-000.098	ELEVATOR	
AMERICAN BRIDGE/FLUOR,	AJV		
Diary:			Dispute
Elevator	098 0-000	0-000.098	2.00
		ndable parts and tools that are required for operating and tools are required per the Contract Special Provisions, but	
	of expendable parts and to		
	L (I D D) ()		
The letter was forward	ed to the DJV for approval		
CCO-355 Bid Item:	00.000	CIC - Elevator Impacts - USA Hoist	
CERTIFIED COATINGS COM	IPANY		
CCO-355 Bid Item:	001 0-CIC-EFA.355	CIC - Elevator Impacts - USA Hoist	
AMERICAN BRIDGE/FLUOR,	AJV		
Labor			
Trade Clas Contractor: AMERICAN BE		RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Semi-Skilled Laborer JNM	RIDGE/FLUOR, A JV CARLOS GARCIA	0.00 0.00 0.00 0.00	
Semi-Skilled Laborer FOR		0.00 0.00 0.00 0.00	
Diary:			Dispute
Elevator Inspection	001 0-CIC	C-EFA.355	-
-			
At 0700, I met Bill O'Sullivan, ABF, and Frank Katalano, Mid-American Elevator, at the Pier 7 boat dock then took the crew boat out to T1 to perform a final punchlist inspection of the elevator.			
	·	•	



Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Feather, Bernard Diary #: 659 Date: 23-Oct-2014 Thursday

We went over the open punchlist items and resolved them as follows:

Item #2: Inspected the antenna cable. The frays and burrs had been removed and the insulation was intact so I bought it off.

Item #14: The top of the elevator cab was clean and the nicks in the paint had been repaired. However, I informed Bill that I would not close this item until all painting of the shaft above the cab was complete and I performed a final inspection.

Item #23: Galvanizing repair was complete on the ladder so I closed this item.

Item #28: The rags and wood strips have been removed from the gap in the pit and cleaned so I closed this item.

Item #55: The Code Data Plates have been installed so I closed this item.

Item # 56: Paint repair and repainting of the machine room floor was complete so I closed this item. There was still assorted parts, tools, and trash in the machine room. Bill said that that would be removed.

Frank K. was present to energize the elevator and move it down from elevation 27M to Elevation 18. Frank performed this work and was off site by 1000.

After the elevator was lowered, ABF laborers Ignacio and Carlos Garcia spent the shift cleaning the cab, pit, and machine room. Sami Daouk's, CT, diary for this day records their activities.

